#### United States of America

## Department of Transportation—Federal Aviation Administration

# Supplemental Type Certificate

Number

SA7232SW-D

This certificate, issued to

Dassault Falcon Jet P.O. Box 967

Little Rock, Arkansas 72203

certifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part

25 of the Federal Aviation

Regulations.

Original Product - Type Certificate Number:

A46EU

**Dassault Aviation** 

Model:

Mystere - Falcon 900

Description of Type Design Change:

Battery Installation (36 or 40 hour) in accordance with Drawing List Report No. F90-01053, Revision G. dated 10-18-01, or later FAA approved revision.

See Page 2.

Limitations and Conditions:

See Page 2.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

May 3, 1988

Date reissued :

Date of issuance:

May 24, 1988

Date amended: 9-27-93, 10-9-01, 11-3-01 Rev. 3

By direction of the Administrator

De S. Reener (Signature) Andrew A. Boersma

DAS8SW COORDINATOR

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

### United States of America

# Department of Transportation—Jederal Aviation Administration

# Supplemental Type Certificate

(Continuation Sheet)

Number SA7232SW-D Revision 3

## Description of Type Design Change (Continued):

- When the -501 installation is utilized: FAA Approved Airplane Flight Manual Supplement, Report No. 36071-1, dated 5-24-88, or later FAA approved revision is required.
- 2) When the -503 installation is utilized:
  - a) FAA Approved Airplane Flight Manual Supplement, Report No. 36071-2, dated 9-27-93, or later FAA approved revision is required.
  - b) Airplane Maintenance Manual Supplement Report No. 36333, dated 8-26-93, or later FAA approved revision is required.
- 3) When the -505 installation is utilized:
  - a) FAA Approved Airplane Flight Manual Supplement, Report No. 36071-3, dated 10-9-01, or later FAA approved revision is required.
  - b) Airplane Maintenance Manual Supplement Report No. 36333, dated 8-26-93, or later FAA approved revision is required.
- 4) When the -507 installation is utilized:
  - c) FAA Approved Airplane Flight Manual Supplement, Report No. 36071-4, dated 11-3-01, or later FAA approved revision is required.
  - d) Airplane Maintenance Manual Supplement Report No. 36943, dated 9-25-01, or later FAA approved revision is required.

### Limitation and Conditions:

- 1) The F90-01053-501 Installation is valid only in the Mystere Falcon 900 Model Aircraft.
- 2) The F90-01053-503 Installation is valid only in the Mystere Falcon 900 Model Aircraft.
- 3) The F90-01053-505 Installation is valid only in the Falcon 900C Definition Aircraft.
- 4) The F90-01053-507 Installation is valid only in the Falcon 900C Definition Aircraft.
- 5) Compatibility of this modification with other previously approved modifications must be determined by the installer.

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office the transfer of this Supplemental Type Certificate.
The FAA will reissue the certificate in the name of the transferee and forward it to him.
TRANSSER FAIRORSTAIRNIT :
TRANSFER ENDORSEMENT
Transfer the ownership of Supplemental Type Certificate Number
to (Name of transferee)
(Address of transferee)(Number and street)
(City, State, and ZIP code)
from (Name of grantor) (Print or type)
(Address of grantor)(Number and street)
(City. State, and ZIP code)
Extent of Authority (if licensing agreement):
Date of Transfer.
Date of Transfer:
Signature of grantor (In ink):